Start flashing firmware [DeviceService] Check BLE Addresses are paired [DeviceService] stop poll UHK Device [DeviceService] stopped poll UHK Device [SmartMacroService] start downloading firmware documentation {"firmware-GitRepo":"UltimateHackingKeyboard/firmware","firmwareGitTag":"v15.3.0"} [SmartMacroService] firmware documentation downloaded earlier [Smart-MacroService] reference manual downloaded earlier [UhkHidDevice] Available devices unchanged [UhkHidDevice] Used device: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1} [UhkHidDevice] productId: 9 protocol versions: {"firmwareVersion":"15.3.0","deviceProtocolVersion":"4.17.0",... [DeviceService] start poll UHK Device [DeviceService] stop poll UHK Device [DeviceService] stopped poll UHK Device [DeviceService] Operating system: Linux 6.17.9-arch1-1 x64 [DeviceService] Agent version: 9.0.0 [DeviceService] New firmware version: 16.0.0 [DeviceService] New firmware user config version: 13.0.0 [DeviceOperation] Read "leftHalf" version information [DeviceOperation] Read "leftHalf" repo information [DeviceOperation] Read "leftHalf" firmware checksum [DeviceOperation] Read "leftModule" version information [DeviceOperation] Read "leftModule" repo information [DeviceOperation] Read "leftModule" firmware checksum [DeviceOperation] Read "rightModule" version information [DeviceOperation] Read "rightModule" repo information [DeviceOperation] Read "rightModule" firmware checksum [DeviceService] UHK Device firmware upgrade starts: {"id":4,"asCliArg":"uhk80-right","firmwareUpgradeMethod":"mcuboot","logName":"UHK 80 right","name":"UHK 80","keyboard":[{"vid":14248,"pid":9}],"bootloader":[{"vid":14248,"pid":8}],"buspal":[],"reportId":4} [DeviceService] Current Device right built firmware checksum: a34f7a1922f4ea594dd16afac57b7f23 [DeviceService] New Device right firmware checksum: 687e471955a79f0a021e94cdfcb01649 [UhkOperations] Start flashing device firmware with mcuboot [UhkOperations] Start flashing UHK 80 right firmware with mcumgr [UhkOperations] Reenumerate bootloader [UhkHidDevice] Device communication closing. [UhkHidDevice] Device communication closed. [UhkHidDevice] Start reenumeration, mode: Bootloader, timeout: 5000ms [UhkHidDevice] Available devices unchanged [UhkHidDevice] Reenumeration error. We hope it would not break the process Error: Cannot write to hid device [UhkHidDevice] closing normal keyboard after reenumeration [UhkHid-Device] Available devices changed. [UhkHidDevice] Removed: {"ven-dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6} [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2} [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1} [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1} [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29... Gadget Laboratories","release":0,"interface":-1} [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialN...

Gadget Laboratories","release":0,"interface":-1} [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHid-Device] Could not find reenumerated device: Bootloader. Waiting... Update for version 9.0.0 is not available (latest version: 9.0.0, downgrade is disallowed). [AppUpdateService] checkForUpdate success [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices unchanged [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6} [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1} [UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting... [UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6} [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2} [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1} [UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6} [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1} [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}

[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29 Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29 Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29 Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29 Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":" Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U

Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"

Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-

dorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw6”,”serialNumber”:”2987475164”,”manufacturer”:”U...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:0,”usagePage”:1,”usage”:6}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw7”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:1,”usagePage”:1,”usage”:2}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw8”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:2,”usagePage”:65280,”usage”:1}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw9”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:3,”usagePage”:12,”usage”:1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {”ven-
dorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw6”,”serialNumber”:”2987475164”,”manufacturer”:”U...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:0,”usagePage”:1,”usage”:6}
[UhkHidDevice] Added: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw8”,”serialNumber”:”29...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:2,”usagePage”:65280,”usage”:1}
[UhkHidDevice] Added: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw9”,”serialNumber”:”29...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:3,”usagePage”:12,”usage”:1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {”ven-
dorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw6”,”serialNumber”:”2987475164”,”manufacturer”:”U...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:0,”usagePage”:1,”usage”:6}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw7”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:1,”usagePage”:1,”usage”:2}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw8”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:2,”usagePage”:65280,”usage”:1}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw9”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:3,”usagePage”:12,”usage”:1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {”ven-
dorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw6”,”serialNumber”:”2987475164”,”manufacturer”:”U...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:0,”usagePage”:1,”usage”:6}
[UhkHidDevice] Added: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw8”,”serialNumber”:”29...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:2,”usagePage”:65280,”usage”:1}
[UhkHidDevice] Added: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw9”,”serialNumber”:”29...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:3,”usagePage”:12,”usage”:1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {”ven-
dorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw6”,”serialNumber”:”2987475164”,”manufacturer”:”U...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:0,”usagePage”:1,”usage”:6}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw7”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:1,”usagePage”:1,”usage”:2}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw8”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:2,”usagePage”:65280,”usage”:1}
[UhkHidDevice] Removed: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw9”,”serialNumber”:”
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:3,”usagePage”:12,”usage”:1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {”ven-
dorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw6”,”serialNumber”:”2987475164”,”manufacturer”:”U...
Gadget Laboratories”,”product”:”UHK 80 Right USB”,”release”:1,”interface”:0,”usagePage”:1,”usage”:6}
[UhkHidDevice] Added: {”vendorId”:”0x37A8”,”productId”:”0x9”,”path”:”/dev/hidraw8”,”serialNumber”:”29...

Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"

Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}

[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29

Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"UI
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-

dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U[
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U[
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U[
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U[
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U[
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U[
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}

[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"Ul
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"Ul
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"Ul
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"Ul
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"Ul
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...

[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Available devices changed. [UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U... Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}

[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Added: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"29
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Waiting...
[UhkHidDevice] Available devices changed. [UhkHidDevice] Removed: {"ven-
dorId":"0x37A8","productId":"0x9","path":"/dev/hidraw6","serialNumber":"2987475164","manufacturer":"U
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":0,"usagePage":1,"usage":6}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw7","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":1,"usagePage":1,"usage":2}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw8","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":2,"usagePage":65280,"usage":1}
[UhkHidDevice] Removed: {"vendorId":"0x37A8","productId":"0x9","path":"/dev/hidraw9","serialNumber":"
Gadget Laboratories","product":"UHK 80 Right USB","release":1,"interface":3,"usagePage":12,"usage":1}
[UhkHidDevice] Could not find reenumerated device: Bootloader. Timeout
[DeviceService] updateFirmware error {"message":"Could not reenumerate
as Bootloader","stack":"Error: Could not reenumerate as Bootloader\n at
ur.reenumerate (/tmp/.mount_UHK.Ag0X4Dhb/resources/app.asar/electron-
main.js:8:583798)\n at process.processTicksAndRejections (node:internal/process/task_queues:105:5)\n
at async ao.updateFirmwareWithMcuManager (/tmp/.mount_UHK.Ag0X4Dhb/resources/app.asar/electron-
main.js:8:615660)\n at async ys.updateFirmware (/tmp/.mount_UHK.Ag0X4Dhb/resources/app.asar/electron-
main.js:8:682253)\n at async cs.process (/tmp/.mount_UHK.Ag0X4Dhb/resources/app.asar/electron-
main.js:8:664678)"} [DeviceService] start poll UHK Device [ZephyrLogService
| UHK Dongle] Enabling [ZephyrLogService | UHK 80 left] Enabling Could not
reenumerate as Bootloader